

### Communication error!

An error occurred while communicating with the TimeFactor device <TF-11376>.

The stompbox is not responding. Please verify that it is still connected. (Error code MessageConstants::sm\_response\_timeout)

Error code [sm\_response\_timeout]

MicroPitch

OK